



L1-3 - 300 nh 11T #18 wound in threads of 1/4-20 machine screw
 C3, C4 - Gimmick Capacitor, wire near center inductor. Adjust for desired BW